This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.















Fig.2B

















FIG. **8**





FIG. **9**







FIG. 11






FIG. 13A




FIG. 13B






FIG. 14








FIG. 16






FIG. 17



Actuation Voltage

Fig · 18







FIG. 20











FIG. 21





















FIG. **25**




Fig·26













Damping and spring forces









Effective area



Area [%]









Fig.36A

Applicant(s): Musalem, et al. Atty. Docket No.: 1488/12/2

Eqn | Z_varactor_HFSS_shorter_input_line=stoz(Tesr_quad_varactor_shorter_input_line..S11)

Eqn C_varactor_HFSS_shorter_input_line=im(Test_quad_varactor_shorter_input_line..Y(1,1)/(2*pi*freq)

Q_varactor_HFSS_shorter_input_line=-im(Z_varactor_HFSS_shorter_input_line)/re(Z_varactor_HFSS_shorter_input_line) Edn



freq=1.000GHz C_varactor_HFSS_shorter_input_line=2.640E-


C_varactor_HFSS_shorter_input_line=2.663E-

freq=2.000GHz

freq=6.000GHz C_varactor_HFSS_shorter_input_line=2.914E-

m24

freq (1.000GHz to 10.00GHZ) Test_quad_varactor_shorter_input_line.. S(1,1)











Fig · 37B

















Fig . 44A









Fig . 44B















FIG. 49







FIG. 51



Z DISPLACEMENT -0.09 -0.06 -0.03 -0.01 0.02

FIG. **52**





Fig · 53A



Fig·53B

Applicant(s): Musalem, et al. Atty. Docket No.: 1488/12/2




Fig.53c